

	Type	L #	Hits	Search Text	DBs	Time Stamp	Com men ts	Er ro r s
1	BRS	L 1	24	((piston same seat same seal) and (422/100.ccls. or (73/864.13-864.18).c cls.)) or (pipet\$6.ti,ab,clms. and (piston same seat same seal))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/05/2 9 14:55		0
2	BRS	L 2	313	((piston same seal) and pipet\$6.ti,ab,clms.) or ((piston same seal) and (422/100.ccls. or (73/864.13-864.18).c cls.))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/05/2 9 17:23		0
3	BRS	L 3	289	2 not 1	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/05/2 9 15:06		0
4	BRS	L 4	328	((plunger same seal) and pipet\$6.ti,ab,clms.) or ((piston same seal) and (422/100.ccls. or (73/864.13-864.18).c cls.))	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/05/2 9 17:23		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	E r r o r D e f i n i t i o n	E r r o r s
5	BRS	L 5	73	4 not 2	USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/05/2 9 17:23			0